



| | | |
|---|----------------------|--|
| Document Name B10 Version Notes | System B10 | Developed for General Distribution |
|---|----------------------|--|

12/19/2007 FPGA 10.0.35 PIC 3.0D

| Problem/Feature | Description |
|------------------|-------------|
| Initial release. | |

1/03/2008 FPGA 10.0.35 PIC 3.0E

| Problem | Description |
|---|--|
| The "beacon message" bug needs to be applied to this version. | The fix has been applied to prevent unpredictable results that might be caused by the bug. |

1/7/2008 FPGA 10.0.35 PIC 3.0F

| Problem | Description |
|--|--|
| The communication lock-up fix reported for the I200 needs to be applied. | This has been traced to a communications state-machine problem which caused the device's communications to lock up under some circumstances. This problem has been fixed by clearing the interrupt flag immediately after a message is read out of the FPGA buffer by the PIC. |