



Document Name <b>B10 Version Notes</b>	System <b>B10</b>	Developed for <b>General Distribution</b>
---	----------------------	--

### 12/19/2007 FPGA 10.0.35 PIC 3.0D

Problem	Module	Description
Initial release.		

### 1/03/2008 FPGA 10.0.35 PIC 3.0E

Problem	Module	Description
The "beacon message" bug needs to be applied to this version.	PIC	The fix has been applied to prevent unpredictable results that might be caused by the bug.

### 1/7/2008 FPGA 10.0.35 PIC 3.0F

Problem	Module	Description
The communication lock-up fix reported for the I200 needs to be applied.	PIC	This has been traced to a communications state-machine problem which caused the device's communications to lock up under some circumstances. This problem has been fixed by clearing the interrupt flag immediately after a message is read out of the FPGA buffer by the PIC.

### 9/15/2008 FPGA 10.0.35 PIC 4.0A

Problem	Module	Description
TriggerPoints, Initiate, and Abort commands need to be added to make the M10 compatible with the new A500 data acquisition.	PIC	These messages have been added. The M10 now implements the new standard for all devices.