



Document Name N2400 Version Notes	System N2400	Developed for General Distribution
---	------------------------	--

1/03/2008 FPGA 10.10.7 PIC 3.0D

Problem	Description
Initial release.	

1/7/2008 FPGA 10.10.7 PIC 3.0E

Problem	Description
The communication lock-up fix reported for the I200 needs to be applied.	This has been traced to a communications state-machine problem which caused the device's communications to lock up under some circumstances. This problem has been fixed by clearing the interrupt flag immediately after a message is read out of the FPGA buffer by the PIC.